


[Software] CinemaPro error message

Applicable Model:

FR600, FX600, FX610, FX610MX, FR600 3D, FX603, FX400, FX700, FR700

- **Symptom:**
 - When we do the display switching by pressing Fn+F2 with external display connected, CinemaPro would stop working, and the system would jump up an error message as below picture.



- **Root Cause:**
 - When switching display, the resolution would change and the older version CinemaPro cannot support that.
- **Solution:**
 - Please update CinemaPro to the latest version 1.0.0.9z to solve this issue.

[Storage] Can't play Blu-ray disc using Corel WinDVD 8 (the AACs key has expired!)

Applicable Model:

All Blu-Ray Models using Corel WinDVD 8

GX600, GX700, GX701, GX705, EX700, EX710, GX710, GX711, ER710, CR630, CX620, CX623, GE600, GT660, GX660, FR600, FX600, FX603, FR700, GE700, CR720, CX705

Q:

I can't play Blu-ray disc using COREL WinDVD 8, there's a pop-ups message saying "The AACs key has expired."

A:

Please download the SOP to update Corel WinDVD8 AACs key from link provided below:

http://www.msi.com/uploads/faq/faq_89dbb1b7e955b4d576d68c3858514508.pdf

FTP site Update

Below is the weekly update information on ftp site.

Update information

BIOS/EC

| Model | BIOS Version | Note |
|--------------------|--------------|--|
| MS-16GK | A16GKAMS.30D | 1. Fixed the problem that system can't run Recovery problem by pressing F3. 2. EC version 16GKEMS1.415. 3. VBIOS version BR036776.003. |
| MS-1688 | E1688IMS.10Y | 1. Update ATI PARK XT VBIOS. |
| MS-1675 | E1675IMS.10I | 1. Issue Fixed: After driver installed, WiMax & WiFi will miss in device manager. |
| MS-16G1 | E16G1IMS.104 | 1. Update MRC to 1.4. |
| MS-1481 | E1481IMS.104 | 1. Update MRC to version 1.4. |
| MS-16G7 | E16G7IMS.102 | 1. Update MRC to 1.4. |
| MS-1751 | E1751IMS.104 | 1. Fix CPU frequency issue. |
| MS-16G4 | E16G4IMS.104 | 1. Fix CPU frequency settings. |
| MS-1688 | E1688IMS.10Z | 1. Update ATI PARK XT VBIOS. |
| MS-1751 | E1751IMS.105 | 1. Update NVIDA VBIOS. |
| MS-163A | E163AIMS.112 | 1. Disable PCIE ASPM L0s and L1. |
| MS-1727 (GX740) | BR35757.027 | 1. VBIOS update. |
| MS-1471 | A1471IMS.50E | 1. Fix the problem that can't browse internet under Windows XP issue. |

| Model | EC Version | Note |
|----------------|--------------|---|
| MS-1675(GE603) | 1675EMS1.022 | 1. First release. |
| MS-16G7 | 16G7EMS1.402 | 1. Modify ECO setting menu which shows wrong information. |